




Chapter 2

Chair

Bottom Rail



A. Weldments Toolbar.

Step 1. Click File Menu > New, click Part and OK.

Step 2. Right click Sketch on the Command Manager toolbar and select Weldments, Fig. 1.

Step 3. Click Weldments on the Command Manager toolbar.




Fig. 1

B. 3D Sketch.

Step 1. Click 3D Sketch on the Weldments toolbar.

Step 2. Click Line (L) on the Sketch toolbar. The cursor should change to XY plane indicating you are sketching in XY plane. If not, press Tab to switch sketch plane.

Step 3. Draw a line from **right to left** on X axis away from Origin




Fig. 2

Step 4. Right click drawing and click Select from menu to unselect Line Tool.

Step 5. Ctrl click line and Origin to select both. Release Ctrl key and click Make Midpoint on the Content menu, Fig. 3.




Fig. 3

Step 6. Click Smart Dimension (S) on the Sketch toolbar.

Step 7. Dimension line 23.25, Fig. 4.

Step 8. Click Zoom to Fit (F) on the View toolbar.




Fig. 4

Step 9. Click Line  (L) on the Sketch toolbar.

Step 10. Press Tab to change sketch plane to YZ plane

 View the Reference Triad  at the bottom left corner of the display to determine the sketch plane.




Fig. 5

Step 11. Draw a line away from first line at an angle or not on Z axis (no Yellow Z), Fig. 5. Cursor

should be  and not 

Step 12. Right click drawing and click Select from menu to unselect Line Tool.




Fig. 6

Step 13. Ctrl click line and right endpoint of first line. Release Ctrl key and click Make Coincident  on the Content menu, Fig. 6.




Fig. 7

Step 14. Click Smart Dimension  (S) on the Sketch toolbar.




Fig. 8

Step 17. Draw vertical centerline down from intersecting lines, Fig. 8. Keep line vertical or on the Y axis

 (yellow Y).





Fig. 9

Step 19. Dimension angle 71 degrees, Fig. 9.

Step 20. Check 3D sketch in Top View. Click Top  on the Standard Views toolbar (Ctrl-5). The second line should be vertical Fig. 10.

Fig. 10

Step 21. Check 3D sketch in Right View. Click **Right**  on the Standard Views toolbar (**Ctrl-4**). Second line should be at angle, **Fig. 11**.



Step 22. Click **3D Sketch**  on the Weldments toolbar to exit 3D Sketch. **Fig. 11**

C. Save as "CHAIR".

Step 1. Click File Menu > Save As.

Step 2. Key-in CHAIR for the filename and press ENTER.

D. Structural Member.

Step 1. Click **Trimetric**  on the Standard Views toolbar.

Step 2. Click **Structural Member**  on the Weldments toolbar.

Step 3. In the Structural Member Property Manager set:

under Standard:
My Profiles, **Fig. 12**

under Type:
Chair Wood

under Size:
2 x 4

click **first line** in 3D
sketch, **Fig. 13**

click **Locate Profile** button,
Fig. 12

click **bottom**
rear corner of
profile sketch, **Fig. 13** and
member moves, **Fig. 14**

set **Rotation**

angle 

19 degrees, **Fig. 12**

press **Tab** key, **Fig. 15**

click **OK**  in the Property Manager.




Fig. 13

Fig. 14

Fig. 15

Step 4. Save. Use **Ctrl-S**.

E. Rename Structural Member1 BOTTOM RAIL.

Step 1. Rename Structural Member1 to BOTTOM RAIL in the Feature Manager, **Fig. 16**. To rename, click Structural Member1 name in Feature Manager and press F2 on keyboard. Key-in **BOTTOM RAIL**.




Fig. 16

F. 3 Point Arc.

Step 1. Click top face of the member and click Sketch on the Content menu, **Fig. 17**.




Fig. 17

Step 2. Click Normal To on the Standard Views toolbar. (Ctrl-8)

Step 3. Click 3 Point Arc (S) in the Arc flyout on the Sketch toolbar.




Fig. 18

Step 4. Draw 3 Point Arc between Points 1, 2 and 3 across bottom of member, **Fig. 18**.

Step 5. Click Smart Dimension



(S) on the Sketch toolbar.






Fig. 19

Step 6. Dimension both the .39's first, then arc 45.15, Fig. 19.

Step 7. Save. Use Ctrl-S.

G. Extruded Cut.

Step 1. Click Weldments  on the Command Manager toolbar.

Step 2. Click Extruded Cut  on the Weldments toolbar.

Step 3. In the Cut-Extrude Property Manager set:

under Direction 1, Fig. 20

End Condition to Through All

The Direction arrow should point towards area to be cut away, Fig. 21. If arrow is pointing in wrong direction, check Flip side to cut,

Fig. 20. Click OK .




Fig. 20




Fig. 21





Fig. 22

H. Chamfer.

Step 1. Click Trimetric  on the Standard Views toolbar.

Step 2. Click Chamfer  on the Weldments toolbar.

Step 3. In the Chamfer Property Manager set:



click top front edge,
Fig. 24

click OK ,
Fig. 25.

Step 4. Save. Use Ctrl-S.




Fig. 23




Fig. 24




Fig. 25

I. Hole Wizard Counterbore.

Step 1. Click Top  on the Standard Views toolbar. (Ctrl-5)

Step 2. Click Hole Wizard  on the Weldments toolbar.

Step 3. In the Property Manager, on the Type tab set:
under Hole Type:

Click Counterbore , Fig. 26

under Standard:

select Ansi Inch

under Size:

select #8

under End Condition:

set Through All

under Options

check Under head countersink

set under head countersink  diameter to .33

Click Positions tab  at top of the Property Manager.

Click to place a hole inside right edge, Fig. 27.

Click to place a second hole.

Step 4. Right click drawing and click Select from menu to unselect Point tool.

Step 5. Ctrl click both Points to select both. Release Ctrl key and click Make Vertical  on the Content menu, Fig. 28.




Fig. 27




Fig. 28

Step 6. Click Smart Dimension  (S) on the Sketch toolbar.

Step 7. Dimension as shown in Fig. 29.

Step 8. Click Centerline  (S) on the Sketch toolbar.

Step 9. Draw a vertical centerline down

from Origin , Fig. 30.




Fig. 29




Fig. 30



Fig. 26

Step 10. Right click drawing and click Select from menu to unselect Centerline tool.

Step 11. Drag a selection around all geometry as shown in Fig. 31.

Step 12. Click **Mirror Entities**

 **Mirror Entities** on the Sketch toolbar, Fig. 32.




Fig. 31




Fig. 32

Step 13. Click OK  in the Hole Wizard Property Manager.



Fig. 33

Step 14. Save. Use **Ctrl-S**.

J. Material Cedar.

Step 1. Click Trimetric  on the Standard Views toolbar.

Step 2. Right click Material  in the Feature Manager and click **Edit Material**, Fig. 34.

Step 3. Expand Woods (click the +) in the material tree and select Cedar, click **Apply** and **Close**, Fig. 35.




Fig. 34

Step 4. Save. Use **Ctrl-S**.




Fig. 35




Fig. 36