

# Set Toolbox Files Properties

## A. sldsetdocprop.exe (SOLIDWORKS Set Doc Properties).

Step 1. If necessary, close any of your toolbox files (Gears) in SOLIDWORKS.

Step 2. Open File Explorer.

Step 3. Navigate to **Program Files/ SOLIDWORKS Corp/ SOLIDWORKS/ Toolbox/ data utilities** folder

open **sldsetdocprop.exe**, Fig. 1.




Fig. 1

Step 4. In the Set Document Property dialog box:  
click **Add Files** button, Fig. 2.

Step 5. In the Open dialog box:  
Navigate to **My Documents/ Tech Ed 24-25/ Solar Sidewinder** folder

**Ctrl click the toolbox parts (2):**  
**GEAR 10T**  
**GEAR 32T**  
and click **Open**, Fig. 3.




Fig. 2





Fig. 3



Step 6 Back in the Set Document Property dialog box:  
 under Set Document Property, **Fig. 4**  
 select **Property state: No**  
 click **Update Status** button.




**Fig. 4**

Step 7. All is good. But, if you want to  
 confirm update, select a file and click  
**Show Selected Property** button,  
**Fig. 5.**


click **Close** button.

Step 8. In an Assembly Feature Tree these  
 files will now show as part icon   
 as opposed to the toolbox icon .



**Fig. 5**

**Tip:** Create a desktop short cut to **sldsetdocprop.exe**.



**Fig. 6**